Southern Trails Area
2008 Calibration Schedule

Steve Farmer 801-324-5670

	Meter #	Meter Name	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
	000162	PG&E Essex (Ultra)	10	14	10	10	15	12	10	14	11	16	13	11
	000163	SoCal North Needles (Ultra)		7	12	9	14	11	9	13	10	15	12	10
	000166	Citizens M&R (Ultra)												
	000180	Mohave Valley Comp Station FG												
	000191	Mohave Valley Compressor Station												

Doug Walters 801-324-4973

	Meter #	Meter Name	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
	000161	Blanco Interconnect (Ultra)	21	18	24	21	19	16	21	18	22	20	20	22
	000169	Red Mesa Station FG	15	5	10	14	12	10	14	11	15	14	10	15
	000170	Cameron Station FG	9	26	4	8	6	5	8	5	9	9	4	2
	000189	Cameron Compressor Station												
	000190	Red Mesa Compressor Station												
	000192	Shiprock Compressor Station												
	000193	Shiprock Station FG	16	7	11	15	13	24	15	12	16	16	11	16
	000919	Red Mesa NTUA	10	6	5	9	7	4	9	6	10	8	5	3
	001104	Tuba City NTUA	8	6	3	7	5	4	7	4	8	8	3	1